

## Cleveland Pump Repair: Recent Projects

Repairs and Service available on all types of industrial pumps. See below for some of our recent projects, work done in our shop or yours.

Equipment Description	Service Function	Market Served	Service Provided
I-R 65CHTA-4	Boiler Feed Water	Power	Repair / FSS Installation
Pacific 6" LM-12 Stg.	Boiler Feed Water	Power	Repair / FSS Installation
A-C 14x16CF2VT	Condensate	Power	Repair
Worthington 12WNC186	Boiler Feed Water	Power	Repair
Worthington 8WC137	Descale	Steel Mill	Repair
Delaval 8BB21310-8Stg.	Boiler Feed Water	Power	Repair / Upgrade / New Couplings
I-R 4x11DA-8 Stg.	Boiler Feed Water	Pulp & Paper	Repair / Field Service Supervision
I-R 60APMA	Circulating Water	Power	Repair
Delaval 7BB31310	Boiler Feed Water	Power	Repair / Full Set New Impellers
Union 6X8 MQE	Descale	Steel Mill	Repair / Upgrades
Hazelton 10" S515-CTE	Slurry Pump	Power	Repair
Foster-Wheeler 48MF-2 Stg.	Circulating Water	Power	Repair / Upgrade / FSS
CH Wheeler 48x54 SAFV	Circulating Water	Power	Repair / New Impeller

I-R 2 1/2 CNTA-6	Boiler Feed Water	Food/Bev.	Repair
Pacific 4" SIJ - 10 Stg.	Decoking	Refining	On-Site Element Change
A-C 6x5 DJ-7 Stg.	Boiler Feed Water	Power	Turn-Key Repair
Union QD-100 Plunger Pump	Lube Oil	Steel Mill	Repair
United S-2x12 TCM	Heater Drain	Power	Repair
Worthington 10L30	Service Water	General Industry	Repair
I-R 25APKD-7	Condensate	Power	Field Service
Worthington 4UJ-2	Heater Drain	Power	Repair
I-R 28APKC-4 Stg.	Hot Well	Power	Repair / Upgrade 1st Stg. Impeller
BJ 1500 VLT-5	Condensate	Power	Repair / Upgrade Impellers
I-R 10x17 J	Ash Sluice Water	Power	Repair / New Impeller
KSB HGM 3/6	Boiler Feed Water	Power	Repair
A-C 6x6 BBDI	Boiler Feed Water	Power	Repair
B-L-H 33x42 SAFV-2 Stg.	Circulating Water	Power	Repair
I-R 10DH3	Ash Sluice Water	Power	Repair
Goulds 10x12 3405	River Water	Refining	Repair
Peerless 36HXB-2 Stg.	LPSWP	Power	Repair / Upgrade / New Impeller

Copus/Wx RLA12L / WDR8 2 Stg.	Boiler Feed Water	Food/Bev.	Turbine & Pump Set Repair
Worthington 66NA	Water	Waste Water	Rotor Repair
BJ 800MQ VLT-6 Stg.	Butane	Refining	Repair / Upgrade
Goulds #36 VIT	Circulating Water	Power	Repair
Wilson-Snyder 6EX5-6 Stg.	Service Water	Power	Replacement Pump
Goulds 3316M	Boiler Feed Water	Minerals/Mining	Field Service
I-R 18VEH	Boiler Circ. Water	Power	Repair / Replace Head Cover
A-C 90X60 WMCC	Circulating Water	Power	FSS / On-Site Repair
I-R 8ALV	Cooling Water	Steel Mill	Case Repair - Mill Split / Line Bore
Peerless 6TU-16	Service Water	Power	Repair
Sulzer-Bingham 4x6x10D MSD	Boiler Feed Water	Power	Inspection
Foster-Wheeler 60" VA K 4.8RS	Circulating Water	Power	Repair / Upgrade / New Impeller/ FSS
BJ DVMX - 8 Stg	Boiler Feed Water	Power	New Replacement Rotor Assy.
I-R 6HMTA-7 Stg.	Boiler Feed Water	Power	Field Service
Worthington 72 MCV-1	Storm Sewer	Waste Water	Repair
Pacific 8" HL - 10 Stg.	Boiler Feed Water	Power	Repair / FSS Installation
Delaval 42X36	Cooling Water	Steel Mill	Repair

I-R 6X13A	Ash Jet Water	Power	Upgraded Pull-Out Brg. Frame
Worthington WDR-8 4 Stg.	Boiler Feed Water	Food/Bev.	Repair
Gearex	Lube Oil	Steel Mill	Repair
BJ 14x14x16 HDB-4 Stg.	Boiler Feed Water	Power	Repair / FSS Installation
Pro Quip Mixers		General Industry	Unit Assembly
I-R 4CHTA-10	Boiler Feed Water	Power	FSS - On-Site Inspection